

8500 53 Scott street Scope and Budget

EXTERNAL

General Notes

All works to comply with specs, architects colour scheme or garden architects plans

FRONT YARD

Landscaper

General clean up and removal of rubbish no green waste to go in the skip bins allow to remove all of the
To provide kerbing to the borders of the newly established garden beds
All trees that are removed must have stumps left below the ground level
Any area that is to be mulched must have three inches of soil removed and the ground sprayed for grass at least two weeks before mulch is put in place
Allow \$300 for the purchasing and planting of plants
Retic system and controller same as the one on the houses (Lawn and garden beds)
Top dress and aerate lawn
General clean up and removal of rubbish

Fencing Contractor

Replace any cracked or broken fencing unless other wise specified replace with same or similar
All gates to be in good working order
Right hand wing fence replace
Cut the boundary fence to angle down from the high level to the lower level

Carport Contractor

Build a carport to one of the ESE Carport design Positioned as specified

Plumber

Move any free standing taps against the house connect any existing or new down pipes to the storm water

Maintenance

Provide new letter box and numbers

Painter

Paint both of the wing fences including the gate
The remaining concrete paths. Don't allow for the ones which will be replaced

Back Yard

Landscaper

General clean up and removal of all rubbish
Cut all over hanging branches on fence line
Cut and edge all grass
Concrete path to the cloths hoist
Service the hoist or replace if needed
Remove the dead tree

Fencing Contractor

Replace any cracked or broken fencing unless other wise specified replace with same or similar
All gates to be in good working order

Plumber

Move any free standing taps against the house connect any existing or new down pipes to the storm water

Maintenance

Place a access gate over the access hole

House

House External

8500 53 Scott street Scope and Budget

Electrician

New oyster light front and rear

1 new circuits breaker with separate R.C.D M.C.B protection for power circuits and R.C.D M.C.B protection for light circuit

1 main earth (no stake required)

Earthing for all existing light points

Safety check and megga test installation

Allow to supply and fit new globes for all new and existing fittings

1 light switch under car port fit weather proof H.P.M 616 light fitting and have it two way switched with font

Provide smoke alarms to comply with by laws

Glazier

New barrier door hung to suit the existing door

Brick Cleaner (if brick)

Light acid clean the extra walls

Painter

To paint all previously painted surfaces and any new as specified (including the front veranda and the inside of the meter box)

All of the external windows

Roof restorers

Full roof restoration and new colour bond gutters and down pipes including those on the carport (connect to storm water if available)

Maintenance

Fix or replace all damaged facia, bargeboard or eaves linings

Replace missing cover batons

Fix or replace Scotia from eaves

Fix tile fillets from side of house

Remove any old brackets, nails or any other obsolete fixtures from barges or facia

Patch the front door and frame

New CCA handrail and spindles opening to suit position of new step out towards the driveway

Quad around the windows where gaps between the window and the bricks

Plumber

Relace the floor waste flaps if in poor condition

Fix any loose pipe work from any where around the house

Re- root any pipes that run over the verandas or steps

All grills over any DG or any other out let must be good condition and replace any that are missing

Fix any cracked or broken DG or any other pipe connections

House Internal

Maintenance

Remove any old brackets, nails, screws or any other unwanted fixtures

If timber floors, all of the quad must be removed and new MDF provided for the painter to paint, but fitted after the floor has been polished

Quad to be laid around the fire place as well

Doors to operate correctly

Replace all of the door furniture including the cupboard doors

Remove all the old floor coverings

New door buffers through out

Front and back doors must have deadlocks and handles that don't interfere with barrier doors

Pin back any loose wall sheets

Reline all the walls to 1350 except for the wall to the immediate right of the front door reline to 2000

Electrician

Replace all light switches

Replace all GPO's with doubles

8500 53 Scott street Scope and Budget

Provide globes for all light fittings
Replace all of the light fittings

Plumber

To provide new gas bayonets if needed and to make all vents comply with Alinta gas

Blind Company

Provide and fit 25mm slim line blinds through out the house

Glazier

To re wire all fly screens
Replace any cracked chipped or missing glass
Service any existing barrier doors or(provide new only for the front)
Provide winders and screens to any suitable windows

Painter

To paint all previously painted surfaces and any new as specified including the inside of the fire places (black) and any built in cupboards inside and out or sand and varnish

Floor sander

Sand and coat all exposed timber floors with three coat polyurethane system

LOUNGE

Maintenance

Close of the door and cut opening as per the drawing

Electrician

4 down lights

Hall Way

Electrician

Fluro

Maintenance

Strip the vinyl off the shelves in the bathroom

Bed room 1

Maintenance

Patch the cupboards so they are in good working order
Insert haning rails
Reline the eastern walls to the height of the metal strip

Bed room 2

Maintenance

Reline walls to 1350
Patch the cupboards so they are in good working order
Insert hanging rails
Sand the rough edges off the doors on the cupboard

Bedroom 3

Maintenance

Reline walls to 1350

KITCHEN (Refer to the drawings)

8500 53 Scott street Scope and Budget

Maintenance

Remove all asbestos and vertical metal jointing strip. Replace with Gyprock and flush ready to paint
Remove plaster rang hood, patch wall, ceiling and cornice
Remove old cupboards, pantry and overhead cupboards allow to patch wall wear cupboards were (using moister resistant behind sink)
Remove old tiles
Patch ceiling grill after old light is removed

Cabinet maker as per the drawing

New bench cupboards with inset sink (supplied by others)
New overhead cupboard
New pantry
New overhead with range hood ducted through roof and flashed

Tiler

Splash back and between bench top and underside of overheads, behind stove

Plumber

Remove old taps and nozzles, disconnect sink
Supply and fit new double inset sink with flick mixer type tap alter waste to suit

Electrician

Replace light switches
Reposition GPO for fridge
2 single 36w fluros with diffusers
Replace single power point
1 single power point for range hood
Supply and fit new g.p.o double
Power supply for the under the bench electric oven

Floor Coverings

Vinyl throughout whole of kitchen (if not suitable to polish)

Bathroom

Maintenance

Strip the walls of all the asbestosis sheets fit villa board and flush ready to paint remove the horizontal metal strip and flush
Remove the skirting tiles and the tiles from the bath up stand

Electrician

1 single 18w fluro with diffuser and 10" exhaust fan switched to together in bathroom

Tiler

From corner left of mirror all way around bath to left hand architrave of door up to metal joint strip with tile and colour as specified
Ledge and face of bath
Floor and skirting
Raise floor waste
Supply and fit cover strip for edge of tiles
All work is supply and fit

Plumber

Remove the old bath replace have the shower and bath nozzle at opposite ends. With the tap sets on the face wall. Run any new pipe work as necessary before the walls are relined.
Remove old basin, taps, shower rose, shower taps and all bath taps and nozzle
Supply and fit replacements

Glazier

Supply and fit p.v window with obscure glass
Supply and fit mirror to full length of existing vanity door and handle
Shower screen

8500 53 Scott street Scope and Budget

Cabinet maker

Make and fix vanity unit free standing 900 x 600 (basin supplied by others)

Painter

Inside and out at existing vanity

Bath recoater

Bath

Toilet

Maintenance

Remove all of the skirting tiles

Provide a new toilet roll holder

Remove all wall coverings

Plumber

Remove pan, seat flush pipes and replace with new as specified

New dual flush system as specified

Above works are only if the existing are in poor condition or are not dual flush (check with supervisor if not

Glazier

Fly wire on window

Laundry

Maintenance

Remove batons from ceiling and flush

Remove cover batons from walls and flush

Remove any tiles

Solid rear door and frame with seal in the laundry gap

Plumber (Broom cupboard is to be on the left handside of the window)

Remove old trough and taps and nozzle

Supply and fit new as specified

New grill for floor waste

Run pipes for washing machine (if needed) allow for conversion as to fit the inset trough with pipes and waste

Supply and fit new taps

Allow to remove any redundant pipes

Glazier

Remove existing wooden window with louvres and replace with half slide and fixed with flywire

Electrician

1 single 36w defuses in laundry

Replace washing machine switch with double GPO vertical check that it is in the right position if a conversion of the washing machine and the trough are to happen

G.P.O for reticulation

Tiler

Allow to retile over the bench cupboard and around the window

Run 1 tile high skirt throughout both toilet and laundry

Floor Coverings

Patch and screed laundry and toilet and lay vinyl complying with specs and colour scheme

Cabinet Maker

Bench cupboard with inset sink (supplied by others) and broom cupboard